Bluetooth compatibility list for factory fit LG navigation units

Applicable models:

cee'd, cee'd SW, pro_cee'd

MY10 - from July 2009 production

Venga

MY10 - from November 2009 production

Sportage

MY11 - from June 2010 production

Sorento

MY11 - from June 2010 production

Performance will vary based on phone software version, coverage and your wireless carrier.

Phones are warranted by their respective manufacturer.

Status: Q3/2010

Phone list

Brand	Model	Telephone software	Incoming call	Outgoing call	Phonebook	Call Lists	Telephone status	
Apple	iPhone	iOS 3.1.3 (7E18)	✓	✓	✓	✓		
	iPhone 3G	iOS 4.0 (8A293)	✓	✓	✓	✓		
	iPhone 3GS	iOS 4.0 (8A293)	✓	✓	✓	✓		
	iPhone 4	iOS 4.0.1 (8A306)	✓	✓	✓	✓		
Blackberry	8100	n/a	✓	✓	✓	✓		
	Bold 9000	v4.6.0.303 (Platform 4.0.0.248)	✓	✓	✓	✓		
	Bold 9700	V5.0.0.442 (Platform 5.1.0.121)	✓	✓	✓	✓		
	Curve 8520	v 4.6.1.314 (Platform 4.2.0.135)	✓	✓	✓	✓		
	Curve 8900	v4.6.1.310 (Platform 4.2.0.0.127)	✓	✓	✓	✓		
	Pearl 9100	v 5.0.0.775 (Bundle 1308, Platform 6.0.0.58)	✓	✓	✓	✓		
	Storm2 9520	v5.0.0.497 (Platform 4.2.0.220)	✓	✓	✓	✓		
HP	HW6915	n/a	✓	✓	✗	✗		
HTC	Desire	2.1-update1 Build No: 1.21.405.2 CL174215 release-keys	✓	✓	✓	✗		
	HD 2	Windows Mobile 6.5 Pro OS ver 5.2.21869 (21869.5.0.82) ROM Ver: 1.72.206.3 (86372) WWE 04/15/10	✓	✓	✓	✓		
	HD Mini	Windows Mobile 6.5 Pro OS ver 5.2.23103 (23103.5.3.3) ROM Ver: 1.07.401.1 (85429 WWE) 3/21/10	✓	✓	✓	✓		
	Hero	Firmware: 2.1-update1 Sw no: 3.32.405.1	✓	✓	✓	✗		
	Legend	2.1 Build 1.31.405.4	✓	✓	✓	✗		
	Tattoo	1.67.405.6	✓	✓	✗	✗		
HTC	Touch 2	Windows Mobile 6.5 Pro CE OS 5.2.21854 (Build 21854.5.0.80) ROM Ver.: 1.28.401.4 (66092) 09/16/09	✓	✓	✓	✓		
	Touch Diamond	n/a	✓	✓	✓	✓		
	Touch Pro	n/a	✓	✓	✓	✓	✗	✗
	Wildfire	Android 2.1-UPDATE1 SW No. 1.14.405.2	✓	✓	✓	✗		
I-mate	K-JAM	n/a	✓	✓	✗	✗	✗	✗
	BL40 New Chocolate	BL40_MSM76XX_V10e-JAN-21-2010-GB	✓	✓	✓	✓		

Performance will vary based on phone software version, coverage and your wireless carrier.
Phones are warranted by their respective manufacturer.
Status: Q3/2010

LG	GC900	n/a	✓	✓	✓	✓		
	GD510 Pop	GD510AT_V10g	✗	✗	✗	✗	✗	✗
	GD900 Crystal	GD900AT_V10c	✓	✓	✓	✓		
	GM210	n/a	✓	✓	✓	✓		
	GU230	n/a	✓	✓	✗	✗		
	GW300	n/a	✓	✓	✓	✓		
	InTouch Max GW620	1.5 Kernel: 2.6.27 Version: GW620-V10b	✓	✓	✗	✗		
	KE850	n/a	✓	✗	✗	✗		
	KE970	n/a	✓	✓	✗	✗		
	KF900	n/a	✓	✓	✓	✓		
	KG800	n/a	✓	✓	✗	✗	✗	✗
	KM555	n/a	✓	✓	✓	✓		
	KM900	n/a	✓	✓	✓	✓		
	M4410	n/a	✓	✓	✗	✗	✗	✗
Motorola	E550	n/a	✓	✓	✗	✗	✗	
	Milestone	2.1-update1 Build : SHOLS_U2_02.31.0	✓	✓	✗	✗		
	RAZRV9	n/a	✓	✓	✗	✗		
	RIZR Z8	n/a	✓	✓	✗	✗		
	ROKR E6	n/a	✓	✓	✗	✗	✗	✗
	U6	n/a	✓	✓	✗	✗	✗	
	V3i	n/a	✓	✓	✗	✗	✗	
Motorola	Z10	n/a	✓	✓	✗	✗		
	5230	v20.0.005 23-3-2010	✓	✓	✓	✓		
	6103	n/a	✓	✓	✗	✗	✗	✗
	6111	n/a	✓	✓	✗	✗	✗	✗
	6131	n/a	✓	✓	✗	✗		
	6230	n/a	✓	✓	✗	✗	✗	✗
	6280	n/a	✓	✓	✗	✗	✗	✗

Performance will vary based on phone software version, coverage and your wireless carrier.
Phones are warranted by their respective manufacturer.
Status: Q3/2010

Nokia	6300	n/a	✓	✓	✗	✗		
	6650	n/a	✓	✓	✓	✓		
	6700	n/a	✓	✓	✓	✓		
	7370	n/a	✓	✓	✗	✗	✗	✗
	7380	n/a	✓	✓	✗	✗	✗	✗
	8600	n/a	✓	✓	✗	✗		
	2700 Classic	v 09.80 02-12-09	✓	✓	✓	✓		
	5800 Xpress Music	n/a	✓	✓	✓	✓		
	6500 Classic	V 9.48 26-01-09	✓	✓	✓	✓		
	7230 Slide	V 06.90 26-02-10	✓	✓	✓	✓		
	C5	031.022 28-Mar-2010	✓	✓	✓	✓		
	E51	n/a	✓	✓	✗	✗		
	E52	034.001 02-Apr-2010	✓	✓	✓	✓		
	E60	n/a	✓	✓	✗	✗	✗	✗
	E61	n/a	✓	✓	✗	✗	✗	✗
	E71	n/a	✓	✓	✗	✗		
	E72	031.023 31-Mar-2010	✓	✓	✓	✓		
	N70	n/a	✓	✓	✗	✗	✗	✗
	N77	n/a	✓	✓	✗	✗	✗	✗
	N82	n/a	✓	✓	✗	✗		
Nokia	N90	n/a	✓	✓	✗	✗		
	N900	10.2010.19-1.205.1	✓	✓	✗	✗		
	N95	n/a	✓	✓	✗	✗		
	N97	V 22.0.110 11-06-10	✓	✓	✓	✓		
	N97 Mini	v 12.0.110 11-06-10	✓	✓	✓	✗		
	X3	V 04.11 09-12-09	✓	✓	✓	✓		
	X6	v 21.0.004 05-06-2010	✓	✓	✓	✓		
Palm	Pre	Palm webOS 1.4.1	✓	✓	✓	✓		

Performance will vary based on phone software version, coverage and your wireless carrier.
Phones are warranted by their respective manufacturer.
Status: Q3/2010

Palm	Treo750V	n/a	✓	✓	✘	✘	✘	✘
Philips	O2 Xda Atom	n/a	✓	✓	✘	✘	✘	✘
Samsung	D600	n/a	✓	✓	✘	✘	✘	✘
	D820	n/a	✓	✓	✘	✘	✘	✘
	D900	n/a	✓	✘	✘	✘	✘	✘
	GT-I8000 Omnia II	Windows Mobile 6.5 Pro CE OS 5.2.21856 (Build 21856.5.0.65) Phone: I8000XXII6 BT SW: 2.0.3	✓	✓	✓	✓		
	i5700 Galaxy Portal	2.1-Update1 Build No.: ECLAIR.XXJCB Phone Ver: i750EXXJC1	✓	✓	✓	✘		
	i5800 Galaxy 3 Apollo	2.1-update1 Eclair.BVJF4	✓	✓	✓	✘		
	i9000 Galaxy S	2.1-Update1 Build No.: ECLAIR Phone Ver: I9000XXJF3	✓	✓	✓	✘		
	S3650 Genio touch	S3650ACIK1	✓	✓	✘	✘	✘	
	S5230 Tocco Lite	S5230XPIK2	✓	✓	✘	✘	✘	
	S5600 Blade	S5600BUIF3	✓	✓	✘	✘		
	S8500 Wave	bada 1.0 1005201728LISJEE	✓	✓	✘	✘	✘	
	SGH700	n/a	✓	✓	✘	✘	✘	✘
	SGHXU600	n/a	✓	✓	✘	✘	✘	✘
	U900	n/a	✓	✓	✘	✘		
	Z540V	n/a	✓	✓	✘	✘	✘	✘
Sharp	GX15	n/a	✘	✘	✘	✘	✘	✘
Siemens	SK65	n/a	✓	✓	✘	✘		
Sony Ericson	810i	n/a	✓	✓	✘	✘		
	G900	n/a	✓	✓	✓	✓		
	K610	n/a	✓	✓	✘	✘		
	K750i	n/a	✓	✓	✘	✘		
	M600i	n/a	✓	✓	✓	✓		
	P1i	n/a	✓	✓	✓	✓		
	S500i	n/a	✓	✓	✓	✓		
	V600i	n/a	✓	✓	✘	✘		
	W705	n/a	✓	✓	✓	✓		

Performance will vary based on phone software version, coverage and your wireless carrier.
Phones are warranted by their respective manufacturer.
Status: Q3/2010

	W880i	n/a	✓	✓	✓	✓		
	W980i	n/a	✓	✓	✓	✓		
	Aino U10	R7BA084prg1223-3004_GENERIC_RA	✓	✓	✓	✓		
	Satio U1	1218-9500_R2AK006 18-02-10	✓	✓	✓	✓		
	Vivaz U5	1224-4699_R2CA024 13-04-10	✓	✓	✓	✓		
	W205	R1CD001 1223-5647	✓	✓	✗	✗		
	Xperia X10 mini E10i	1.6 Build no.: 1.0.A.1.36	✓	✓	✗	✗		
	Xperia X10i	1.6 Build: R2BA020	✓	✓	✗	✗		

n/a - telephone software tested before 06/2010

Troubleshooting guide

Problem	Solution
Contacts from SIM card are not displayed in car.	The Multimedia Navigation system cannot display contacts stored on SIM card. Please copy contacts from your SIM card to mobile phone
Phonebook is displayed partially or is not available at all.	The Multimedia Navigation system supports contact numbers stored as Mobile, Home, and Office. Numbers stored as General, Main, Other, etc are not displayed. Please check contact numbers in your phone and if required change category of the number to one of: Mobile, Home, Office.
	The Multimedia Navigation system can display one number per category. If your contacts have multiple numbers in one category (for example Mobile), only one of them will be displayed.
Microphone is not working.	Please check microphone status on the Multimedia Navigation system display. Activate the microphone if required.
Cannot handle multiple calls.	Multiple calls are not supported by the Multimedia Navigation system.
Bluetooth search does not find iPhone.	To pair an iPhone, please set the Multimedia Navigation system to external authorisation mode and perform pairing from the phone.

Performance will vary based on phone software version, coverage and your wireless carrier.
Phones are warranted by their respective manufacturer.
Status: Q3/2010